




SENSOR SENSITIVITY DEVIATION OVER TEMPERATURE

AC102 | AC104 | A116 | AC150 | AC154 | AC184 | AC202 | AC211 | AC216

Deviation in Output Sensitivity (%) vs. Temperature at 100 Hz



This chart illustrates the average deviation of the sensor's nominal sensitivity as a function of temperature.