


WIRING DIAGRAM
 CTC STANDARD M12 TRIAXIAL SENSORS



4 Pin M12

- Pin 1 Axis Y
- Pin 2 Axis X
- Pin 3 Axis Z
- Pin 4 Common

