


1. Attach the TCEB330 Series accelerometer to mounting magnet.




2. Using the included 7/64 in. Allen wrench, loosen the screws and remove the front portion of the grip.



3. Place the base of the accelerometer into the opening of the grip. **Ensure that the triaxial accelerometer is in the desired orientation during placement.**



4. Replace the front of the grip and tighten screws.



5. Attach the J4C connector to the threaded barrel of the accelerometer, and tighten down cable tie and clip off loose end.

